


CX7

Cable to Rail Bond to base of rail (foot)

Conductor A mm ²	Metal Powder (g)	Graphite Mould Type	Handle Clamp Type
50	45	CX7L- E-50	HCC
50	45	CX7R- E-50	HCC
70	45	CX7L- E-70	HCC
70	45	CX7R- E-70	HCC
120	65	CX7L- E -120	HCC
120	65	CX7R- E -120	HCC
150	90	CX7L- E -150	HCC
150	90	CX7R- E -150	HCC



Tools Request :



Mould




Mould brush



Handle clamp



Scraper



Metal powder



Steel disk



Flint igniter



Bus bar brush