

PCE Americas Inc.
711 Commerce Way
Suite 8
Jupiter
FL-33458
USA
From outside US: +1
Tel: (561) 320-9162
Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english www.pce-instruments.com

Technical Light Meter PCE-174

PCE-174 Lux Meter for measuring light with software and interface

The PCE-174 Lux Meter with memory for up to 16,000 readings is used for measuring light in industry, agriculture, and research. The Lux Meter is also used for determining illumination in the workplace, shop window displays, and by designers. It meets with all international standards within the category for Lux Meters.

The Lux Meter displays measurement results in lux and FootCandle. Please consider that 1 FC is equal to 10.70 lux. The device automatically detects the peak value, when this value is retained for a minimum 10 μ s. Thanks to the possibility of selecting the measurement range, the PCE-174 Lux Meter converts into a high precision instrument that is easy to use. The Lux Meter can also be used by inexperienced personnel. Of course, when light is being measured, the ambient conditions must be taken into consideration. As such, the distance must be fixed and the angle between the Lux Meter and the object being measured to obtain result of the highest repeatability.

- Easy to use
- Minimum, maximum and hold functions
- Backlight display
- 3 3/4 digit LCD; with 41 segment graphic bar
- Displays readings in lux or FootCandle
- Battery level indicator
- Auto shut-off
- The Overload indicator shows when the measurement range has been exceeded

Technical specifications

Ranges 40.00 / 400.0 / 4000 / lux

40.00 / 400.0 klux

40.00 / 400.0 / 4000 / fc

40.00 kfc

Resolution 0,1 / 1 /10 / 100 lux

0,01 / 0,1 / 1 / 10 FootCandle

Accuracy $\pm 5\%$ of reading ± 10 digits (<10,000 lux)

 $\pm 10\%$ of reading ± 10 digits (>10,000 lux)

Repeatability ±3%

Memory 16.000 readings

Rate of measurement between 2 seconds and 9 hours

Overload indicator OL = Overload

Screen refresh rate 1.5 per second

Operating conditions 0 to 40°C / 32 to 104 °F / 80% r.h.

Display 3¾ digit LCD

Power 9V battery

Dimensions Device: 203 x 75 x 50mm / 7.9 x 2.9 x 1.9 in

(width x height x depth)

Light sensor: 115 x 60 x 20mm / 4.5 x 2.3 x 0.7 in

(width x height x depth)

Cable length: 150cm

Weight 280g / 9.8 oz

Standards Safety: IEC-1010-1; EN 61010-1

EMV: EN 50081-1; EN 50082-1 corresponding with DIN 5031; DIN

5032

Delivery Contents:

1 x PCE-174 Lux Meter

1 x light sensor

1 x software

1 x USB cable

1 x battery

1 x carrying case

1 x user's manual